Set basic KNX AP Multi WH

Item no.: 9070900



Accessories
Presence detectors

Description

- Basic unit multi-sensor KNX (only air quality sensor)
- Only for using in combination with an existing the Prema S/P KNX presence detecor
- Multi-sensor KNX
- Measures CO2 level, relative humidity, temperature and barometric air pressure
- Three independent, configurable thresholds for the CO2 level and relative humidity
- Integrated individual room thermostat
- 4 binary inputs
- Measuring range CO2: 300 5000 ppm
- Measuring range temperature: -5 °C ... +45 °C
- Measuring range humidity: 1-100~% rF
- Air pressure: 30000 110000 Pa

